	T. A.					BE CALLE	TO C.P.	, v	25X1A	Rev 5/31	1/67	6P,2901)
**************************************	1	2	3	4	5	6	*7	8 ,	9	10	*11	- 12
	DCM Alert Mtn to start generatio	Initial Briefing	Select Acft & Assign Fackage	Mtn to Secure Nitrogen Oxygen	POL to Secure fuel trucks	DCM Mtng with Contract Pers	Mission	Receive Ruel Load fm Flt Plan	I ers Eqp P/U LOX fm POL		TEB,LOX & Refuel #1 & #2	ARC-50 Codes to DCM
-HOUR	H-24 H-23:30	H-23:30	H-23:30 H-22:30	H-23:00	H-23:00	H-22:30	# -22 :30	H-22:30	H-22:00	H-22:00	H-22:00 H-19:00	H-22:00
LOCAL TIME	1125		1155	1 1 4		, i x					1325	
		1300	1255	1225	1225	1330	1255	1255	1325	1325	1625	1325
ACTUAL										-		
THE				1			1	1	1			4.7
LINE /174			7.75				·				, r	
Z ACTUAL	13	14	15	*16	*17	18	19	*20 -	*21	22	25X 23	(1A 24
Z ACTUAL	13 COMMO & IFF Prefit	Install Instr	Select Recovery Crew &	INS	*17	Pkg Data avail fm	INS Data	Pkg Loaded in Acit	MP.; Install	Pkg Data	23 INS Data Prepared	24
2 ACTUAL	COMMO & IFF Preflt	Install Instr	Select Recovery	INS	*17	Pkg Data avail fm	INS Data	ikg Logded	SEP Install checked out & Beacon	Pkg Data	23 INS Date	24
2 ACTUAL IME I'LY X1D -HOUR	COMMO &	Install Instr H-20:00	Select Recovery Crew & give to DCM H=20:00	INC Practy	H-16:00	Pkg Data avail fm	INS Data	Pkg forded in Acft #1 & #2 H-13:00	SIP Install checked out &	Pkg Data	23 INS Data Prepared for Loading	24
Z ACTUAL	COMMO & IFF Prefit H-22:00	Install Instr H-20:00	Select Recovery Crew & give to DCM H=20:00	TRS Precit	H-16:00	Pkg Data avail fm Flt Plan	INS Data avail fm Flt Plan H-12:45	Ekg Ebscled fin Acft #1 & #2 H-13:00 H-8:30	Install checked out & Beacon Check H-11:00 H-8:30	Pkg Data Loaded	INS Data Prepared for Loading	POL Send
Z ACTUAL THE VLY X1D HOUR	COMMO & IFF Prefit H-22:00 H-18:00	Install Instr H-20:00 H-18:00	Recovery Crew & give to DCM H-20:00 H-16:00	HS PadClt H-18:00 U-16:00	H-16:00 H-13:00	Pkg Data avail fm Flt Plan	INS Data avail fm Flt Plan H-12:45 H-12:00	Ekg Sommed fri Acit fri & f2 H-13:00 H-8:30	IP Install checked out & Beacon Check H-11:00	Pkg Data Loaded H-11:00 H-8:30	INS Data Prepared for Loading	POL Send
2 ACTUAL IME IVAY X1D HOUR CAL TIME	OMMO & IFF Prefit H-22:00 H-18:00	Install Instr H-20:00 H-18:00	Select Recovery Crew & give to DCM H-20:00 H-16:00	IRS Precit H-18:00 N-16:00	H-16700 H-13800 /925 2225	Pkg Data avail fm Flt Plan H-13:45	INS Data avail fm Flt Plan H-12:45 H-12:00	Ekg Ebscled fin Acft #1 & #2 H-13:00 H-8:30	JiP Install the cked out & Beacon Check H-11:00 H-8:30	Pkg Data Loaded H-11:00 H-8:30	INS Data Prepared for Loading H-11:00 H-6:00	POL Send
2 ACTUAL IME / L X1D -HOUR	OMMO & IFF Prefit H-22:00 H-18:00	Install Instr H-20:00 H-18:00	Select Recovery Crew & give to DOM H-20:00 H-16:00	H-18:00 9-16:00 1/725	H-16,00 H-13,00	Pkg Data avail fm Flt Plan H-13:45	INS Data avail fm Flt Plan H-12:45 H-12:00	Ekg Sommed fri Acit fri & f2 H-13:00 H-8:30	JiP Install the cked out & Beacon Check H-11:00 H-8:30	Pkg Data Loaded H-11:00 H-8:30	INS Data Prepared for Loading H-11:00 H-6:00	POL Send

	25 Crew	36 Mtn call	INStragon	- 28 Pers		,* 30	31	3 2	· 33	34	35	*36
	Chief	Security	Top Off	Ecp	Acft Status	Start INS	4.1.14	Pkg I Helium	View- finder	INS Data	Engi neer	
·	Standby	to Sterlize		Indiced		HECK OP		Purge	loaded	Tape	Cock Acft	Start, Fower
(1D		Cockpit			CC, INS,			Q-Bay	with film	Loading		oditch &
	77.1.00		×		& DCM				1111			Cowcout #1
H-HOUR	H-4:00 H-Hour	H-4:00 H-3:30	H-4:00 H-3:30		H-3:30	#43130:L	41.501	H-2:00	H-2:00	H-2:00	H-1:30	H-:35
<u> </u>									H-1:30	H-1:30	H-1:00	B=35
CAL TIME	0725	0725	0725	0755					0925	0925	2000	
	1125	0755	0755	0825	0755	0755		0925	0955		0755	1050
#1 ACTUAL TIME			- k		X - 1			72.7	10795	1933 1933	11)25	1110
			7			1 10		4	 			*
115113				L /								
#2 ACTUAL												
#2 ACTUAL									14			
#2 ACTUAL TIME				δ\								
#2 ACTUAL	37	38		, p) +								
#2 ACTUAL	Taxi &	Monk Rec		A				Ť				
#2 ACTUAL		Monk Rec		31 - 2								
#2 ACTUAL	Taxi &	Monk Rec & gather		. 84 - L.								
#2 ACTUAL	Taxi &	Monk Rec & gather Rec		<i>y</i> 1 ·								
#2 ACTUAL TIMB	Taxi & Take Off	Monk Rec & gather Rec : Gear H-Hour								+		
#2 ACTUAL TIME	Taxi & Take Off	Monk Rec & gather Rec ? Gear						*				
#2 ACTUAL TIME H-HOUR	Taxi & Take Off H-:15 H-Hour	Monk Rec & gather Rec : Gear H-Hour					2					
#2 ACTUAL TIME H-HOUR	Taxi & Take Off H-:15 H-Hour	Monk Rec & gather Rec Gear H-Hour H+1:00										
#2 ACTUAL TIME I-HOUR CABUTUAL IME ACTUAL	Taxi & Take Off H-:15 H-Hour	Monk Rec & gather Rec Gear H-Hour H+1:00										
#2 ACTUAL TIME L-HOUR SCALUT AL IME ACTUAL	Taxi & Take Off H-:15 H-Hour	Monk Rec & gather Rec Gear H-Hour H+1:00										
#2 ACTUAL TIME I-HOUR CABUTUAL IME ACTUAL	Taxi & Take Off H-:15 H-Hour	Monk Rec & gather Rec Gear H-Hour H+1:00										

			round For	Dologoo 20	moi.	CIA-RDP69	PAKE-OFF	023000500	H-HOUR 05-4			
		Арр	TOVER LOLI	Resease 20	JU 1/U4/20: *	COLUMN TO CO	2000					
		•	**		7	Walter Commencer			25X1A	Rev 5	/31/67	*
	39	. 40	41	42	43	44	45	46	47	48	49	50
	Standby Spare Acft & Start Engines	Unload Pkg & INS from Spare Acft	Spare Acft Declas	Remove View- finder Film & Map fm Spare	Land & Cool Mission Acft	Secure Mission Acft & Service Engine Oil	SCDM Tape Removed & Given to SIP	Remove View- finder Film & Maps	Remove Tape	Acft Mtn Debrief	Remove Instr	Move Acft In Eangar
H-HOUR	H+:25	H+:30 H+2:30	H+2:30	H+2:30	L+:30	L+:30 L+1:15	L+:30 L+1:15	L+:30 L+1:15	L+:30 L+1:15	I+:45	L+1:00	L+1:15 L+1:30
AL TIME	1150	1155	1"	1000								
#1 ACTUAL	11.20	/355	1355	1355								
#2 ACTUAL					-							
TIME												
TIME	51	252	X1A 53	54	55	25X1A 56	25. 57	X1A 58	59	60	61 2	5X1A
TIME	Unload Pkg & Prepare "TAKE"		53 SCDM Data to Flt Plan	SIP Data to	55 Declass Mission Acft		57 Pkg Submit		59 INS/SCIM Tab Run to Security	Send SCDM Tape to	INS Submit	5X1A
TIME H-HOUR	Unload Pkg & Prepare "TAKE"	INS Erase Data fma Computer	SCDM Data to Flt Plan for	SIP Data to OPS	Declass Mission	56 Pkg "TAKE" to	57 Pkg Submit	58	INS/SCIM Tab Run to	INS Send SCDM	IMS Submit DCM	5X1A
	Unload Pkg & Prepare "TAKE"	INS Erase Data fma Computer	SCDM Data to Flt Plan for	SIP Data to OPS L+3:30	Declass Mission Acft	56 Pkg "TAKE" to Security	57 Pkg Submit	58 Security	INS/SCIM Tab Run to Security	INS Send SCDM Tape to Security	INS Submit DCM	5X1A
H-HOUR	Unload Pkg & Prepare "TAKE"	INS Erase Data fma Computer	SCDM Data to Flt Plan for	SIP Data to OPS L+3:30	Declass Mission Acft	56 Pkg "TAKE" to Security	57 Pkg Submit	58 Security	INS/SCIM Tab Run to Security	INS Send SCDM Tape to Security	IMS Submit DCM	5X1A

NNNW

Approved For Release 2001/04/20 : CIA-RDP69B00041R002300050005-4

ZCZC 044

653/1320452

BT

XXXXX

25X1A

laker K

25X1A

689# TOPSECWET 1320372 CITE

FRIOR ITY

INFO PRIORITY

25X1A 25X1A

25X1A

Info

Section Comdr DCS DCO (2) DCM (2)

Secur

Admin Medic

Finan

R&D

Commo HGR HGR/M H-1 H-2E H-2P

H-2M

H-6H

OXCART /BLACK SHIELD

- 1. CONFIRMING TELECON
- A. BLACK SHIELD MSN BBR BX6714 ALERTED FOR 15 AUG. REQUEST MILAIR FOR FAST MOVEMENT OF TAKE TO BE IN PLACE AT KADENA FOR ETD OF 12202/15AUG.
- 3. IN EVENT MILAIR ITINERARY PROVIDES FOR DIRECT FLIGHT TO 25X1A ROCHESTER, HOS WILL ARRANGE FOR DELIVERY OF FROM ROCHESTER.

TOFSECRET

BJ.